

## Waste Site Reclassification Form

Date Submitted: 03/20/2008	Operable Units: 200-UR-1	Control Number: 2008-026
Originator: CR Webb/ Chris Wollam	Waste Site ID: 600-260	
Phone: 373-5573	Type of Reclassification Action:	
	Closed Out: <input type="checkbox"/> Interim Closed Out: <input type="checkbox"/>	
	No Action: <input type="checkbox"/> RCRA Postclosure: <input type="checkbox"/>	
	Rejected: <input checked="" type="checkbox"/> Consolidated: <input type="checkbox"/>	

This form documents agreement among parties listed authorizing classification of the subject unit as Closed Out, Interim Closed Out, No Action, RCRA Postclosure, Rejected, or Consolidated. This form also authorizes backfill of the waste management unit, if appropriate, for Closed Out and Interim Closed Out units. Final removal from the NPL of No Action and Closed Out waste management units will occur at a future date.

**Description of Current Waste Site Conditions:**

(Summarize status of investigation/remediation of the waste sites.)

The site was reported to the WIDS database as a suspect waste site in March 1999. Originally, the site was an area surrounded with four metal posts and a discolored magenta and yellow rope, with a slight depression in the center. The center of the depression had a flat piece of wood on the ground and two more metal posts. Debris at the site included wire and deteriorated plastic. No signs were posted on the rope. The site was not within any larger posted Underground Radioactive Material area. The purpose of the posts and rope have not been determined. It is not known when the area was delineated, but the rope was badly deteriorated in 1999. Due to the yellow and magenta rope being present, the area was treated as if it were a Contamination Area during the initial investigation on March 25, 1999. A radiological survey was conducted on March 26, 1999. No radiological readings above background were found on the ground, vegetation, a wooden board, plastic debris or ants under the wooden board. When the area was determined not to be contaminated, the ropes and posts were taken down by the Radiological Control Technician. The wooden board and rope were removed from the site.

**Basis for Reclassification:**

(For closeout, reference supporting documentation, as listed in Table 3.)

600-260 was Reclassified to No Action in 2004. This site is listed on Table A-2a, 200-UR-1 Operable Unit Waste Sites That are Identified as Rejected or No Action, DOE/RL-2004-39, Rev. 0, 200-UR-1 Unplanned Release Waste Group Operable Unit Remedial Investigation/Feasibility Study Work Plan. In 2007 the definitions for "Rejected" and "No Action" were revised. The classification of this site should be changed to "Rejected" to align with the revised definitions in the TPA-MP-14 procedure.

**Waste Site Controls**

Engineered Controls: Yes ☐ No ☒ Institutional Controls: Yes ☐ No ☒ O&M requirements: Yes ☐ No ☒

If any of the Waste Site Controls are checked Yes specify control requirements including reference to the Record of Decision, TSD Closure Letter, or other relevant documents.

<i>Tom Fletcher &amp; Brent Chapman</i> DOE Project Manager	<i>Jan 2</i> Signature	<i>JMR 7/16/08</i> Date
<i>John B. Price</i> Ecology Project Manager	<i>John B. Price</i> Signature	<i>7-28-2008</i> Date
_____ EPA Project Manager	_____ Signature	_____ Date

**RECEIVED**  
JUL 29 2008  
EDMC